

SAMPLE REPORT — This is an example of the photo report sent to clients after every vessel check. Vessel details and photos are illustrative. Real reports are delivered within 24 hours of each visit.

Vessel Check Report

Vessel Name	Moondancer
Vessel Type	Beneteau Oceanis 38 — Sloop
Berth	Pontoon C, Berth 14 — Puerto Guardamar del Segura
Owner	Mr & Mrs J. Harrison (Shrewsbury, UK)
Check Date	Monday 12 May 2025
Check Time	09:45
Inspector	Costa Blanca Yacht Care
Report Reference	CBYC-2025-047
Service Plan	Standard Monthly Retainer
Next Scheduled Check	Monday 26 May 2025

OVERALL STATUS

All clear


No significant issues found during this visit. One minor item noted for monitoring (see Bilge section). No immediate action required.

1 — EXTERIOR & DECK

Item	Status	Notes
Hull (visible topsides)	OK	No visible damage or impact marks. Antifouling line clean.
Deck surfaces	OK	Clean and dry. No standing water or debris.
Cockpit	OK	Clear. Cockpit drain flowing freely.
Bimini / Sprayhood	OK	Cover intact, no tears. Secured correctly.
Running rigging	Monitor	Genoa sheet shows minor chafe at clutch point. Not urgent — recommend inspection on next owner visit.
Standing rigging (visual)	OK	No obvious movement or corrosion at chainplates. Forestay and shrouds visually secure.
Anchor & chain	OK	Anchor stowed, chain secured. Locker dry.
Navigation lights (visual)	OK	All covers in place and undamaged.

Mooring lines & fenders	OK	Lines secure and undamaged. Two fenders in place. No chafe observed.
-------------------------	----	--


Exterior Photos




Full length from pontoon



Full length from pontoon




Looking aft from bow



Looking forward



Clutch area close-up



Cleat detail, both sides

2 — BELOW DECKS & INTERIOR

Item	Status	Notes
Companionway & hatch seals	OK	Hatches closed and dogged. No evidence of water ingress.
Saloon & cabin	OK	Dry. No mould, damp patches or odours. Cushions undisturbed.

Bilge (main)	Monitor	Low-level water present (~10cm). Normal for type in warm weather but noted. No smell of diesel or oil.
Bilge pump (auto float switch)	OK	Switch moves freely. Pump tested — operational.
Floorboards	OK	Lifted and checked. Dry beneath.
Galley area	OK	Seacocks closed. No leaks visible. Gas locker empty per owner instruction.
Heads compartment	OK	Seacock closed. No odour.
Forward cabin	OK	Dry. Hatch sealed. No condensation.
Flares & safety equipment	OK	Not inspected this visit — full safety check due August per agreed schedule.

Below Decks Photos



Main bilge

Showing water level



Bilge pump float switch

Close-up



Saloon — looking forward

General condition



Companionway seal

Hatch closed

Showing water level

Close-up

General condition

Hatch closed

3 — SYSTEMS & MECHANICAL

Item	Status	Notes
Battery bank (house)	OK	Reading 12.7V at rest. Healthy. Solar top-up confirmed active.
Battery bank (engine start)	OK	Reading 12.6V. Healthy.
Shore power connection	OK	Not connected this visit (per owner preference).

Engine bay (visual)	OK	No oil or water in bilge. No unusual odours. Seacock closed.
Fuel tank (visual gauge)	OK	Approximately half full. No diesel smell.
Seacocks (all)	OK	All closed per owner instruction. Valves turn freely.
VHF / electronics	OK	Not powered this visit. Equipment covers in place.


Systems Photos




Showing voltage readings



General view, clean and dry



Current level




All closed


4 — MARINA & BERTH

Item	Status	Notes
Berth condition	OK	Pontoon clear. No debris alongside.
Neighbouring vessels	OK	No contact or pressure on fenders from adjacent boats.
Fender positions	OK	Two fenders correctly positioned starboard side.
Lines — bow	OK	Secure. Good tension. No chafe.
Lines — stern	OK	Secure. Good tension. No chafe.
Lines — springs	OK	Both in place and correct.
Tidal movement	OK	Normal for time of year. No concerns.


Berth & Mooring Photos




Port side, full length



Cleat detail



Cleat detail



Starboard side

5 — CONDITIONS & WEATHER NOTE

Conditions at visit	Clear skies. Light northerly breeze ~8 knots. Air temp 24°C. Sea state calm.
Recent weather	Settled conditions over the past two weeks. No significant rain or gales.

Forecast (next 7 days)	Stable. Light to moderate southerly winds mid-week. No adverse weather forecast.
Weather-related observations	None. Vessel showing no effects from recent conditions.

6 — ITEMS FOR ATTENTION

Priority	Item	Detail	Recommended Action
Monitor	Genoa sheet chafe	Minor wear at starboard clutch. Not urgent.	Inspect or rotate sheet on next owner visit.
Monitor	Main bilge water level	Low level (~10cm). Pump working. No odour.	Will check again at next visit.
Scheduled	Safety equipment check	Due August 2025 per service schedule.	CBYC will arrange and confirm date in July.

7 — INSPECTOR'S NOTE

Moondancer is in good condition for this time of year. The bilge water level is worth keeping an eye on as temperatures rise through summer — we'll measure it again at the next visit and let you know if it's changed. The genoa sheet chafe is very minor and not a safety issue, but worth addressing before your next sail. Everything else is as it should be. No concerns. Next check scheduled for Monday 26 May. As always, message us any time if you have questions.

Checked by	Costa Blanca Yacht Care
Service area	Guardamar del Segura · Santa Pola · Torrevieja
Report issued	12 May 2025
Next check	26 May 2025
Contact	hello@costablancayachtcare.es · costablancayachtcare.es